



Peter Thiel
Chief Operating Officer

+61 447 267 677
PETER.THIEL@SYDNEYZOO.COM

PO BOX 40 DOONSIDE
NSW 2767 AUSTRALIA

27 February 2020

Compliance
Department of Planning NSW

By e-mail: compliance@planning.nsw.gov.au

To whom it may concern,

**RE: SSD 7228 Sydney Zoo Independent Environmental Audit Report
RESPONSE TO AUDIT FINDINGS**

We refer to the above matter and provide the following responses to the Audit Findings (using the reference numbers from the audit report):

Z27: the As Built Drawings were not available at the time of the audit, however, are now available and they confirm the construction of the roads, driveways and parkings were in accordance with AS2890.1 and AS2890.2.

Z49: Sydney Zoo relies on the certificates provided by the consultants that the material was acceptable.



PO BOX 40 DOONSIDE
NSW 2767 AUSTRALIA

Z81: the project was delayed due to circumstances beyond the control of the Applicant which caused a delay in the engagement of the Environmental Auditors.

Z221: The applicant confirms that Sediment controls were in place during the course of the project, and the records are held by the contractor, however, the Applicant has not been able to obtain a copy of the PESCPs at the time of the audit. No sediment issues occurred during the build.

Z284: The Recommendation is noted and the additional nesting boxes will be installed.

Should you require any further information, please do not hesitate to contact the writer.

Regards,

A handwritten signature in blue ink, appearing to read "Peter Thiel".

Peter Thiel